

# Ultrasonic Testing of the 120" Dome Truck Axles

September 22, 2006

Truck #	Truck Size	South Wheel	North Wheel
1		ok	ok - P/R
2		ok	ok
3	big	ok	NT
4	big	NT	NT
5	big	NT	ok
6	big	NT	NT
7	big	NT	NT
8	big	NT	NT
9		watch - P/R	ok
10		Fix soon - P/R	Fix - P/R
11		Fix now	ok
12		Recently repaired - NT	Fix
13		Recently repaired - NT	watch
14		watch	Recently repaired - NT
15		ok	ok
16		Fix Now	ok
17		ok	watch
18	big	NT	ok
19	big	NT	NT
20	big	NT	NT
21	big	NT	ok
22	big	NT	NT
23	big	NT	NT
24		ok	ok
25		ok	ok
26		ok	ok
27		ok	Fix
28		ok	ok
29		ok - P/R	ok - P/R
30		ok - P/R	Fix soon

P/R = Previously replaced axle  
 NT = Not Tested  
 Big = Axle on large trucks